Dart Aerospace Ltd. Tuesday, 02/10/2007 12:55:24 PM Linda Lacelle User **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : ARM Job Number : 34965 : 12882 **Estimate Number** : DZ/10/2007 P.O. Number Part Number : D3560042 : D3560 UNDER REVIEW S.O. No. : 4 This Issue **Drawing Number** : N/A Prsht Rev. : NG Project Number : MA : SMALL /MED FAB First Issue : B Type **Drawing Revision** Al4. : 34475 **Previous Run** Material **Due Date** : 09/10/2007 Qty: 5 Um: Written By Checked & Approved By Comment : Est Rev:A New Issue 07.05.24 EC **Additional Product** Job Number: Seq. #: Machine Or Operation: Description: 1.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 PULL FROM STK: 07.10.03 2.0 D3560042 ARM WELDMENT Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) ARM WELDMENT B.32445 D35921 3.0 PLATE Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) PLATE 3 LARGE FAB 4.0 LARGE FABRICATION RESOURCE 1

INSPECT WORK TO CURRENT STEP


Comment: LARGE FABRICATION RESOURCE 1

1-Weld assembly as per dwg D3560

5.0 QC5

Comment: INSPECT WORK TO CURRENT STEP


Each



Date: Tuesday, 02/10/2007 12:55:24 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 34965 Part Number: D3560042 Job Number: Seq. #: Machine Or Operation: Description: VISUAL WELDING INSPECTION 6.0 QC9 Comment: VISUAL WELDING INSPECTION 7-10-04 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 07.10.04 Chemical Conversion Coat as per QSI 005 4.1 8.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 10.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: WH FINAL INSPECTION/W/O RELEASE 11.0 Comment: FINAL INSPECTION/W/O RELEASE 10/1800 Job Completion

Form: rprocess

Page 2




D3560-1 ARM (-041, SHOWN)
OR D3560-2 ARM (-042, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-3 ARM (-043, SHOWN)
OR D3560-4 ARM (-044, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE) D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)





DETAIL A (SCALE 1:1)

GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES



	С		07.06.19	REMOVE POWD	ER COAT
	B 07.01.15 A 06.09.25		REDESIGN AS WELDMENT, ADD POCKETS NEW ISSUE		
COPYRIGHT @ 2006 BY DART AEROSPACE LTD.	DESIGN	9	DRAWN BY	DART	DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKED	#	APPROVED #	DRAWING NO. D3560	REV. C SHIET 1 OF 3
OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	07.06.19			ARM WELDMENT	SCALE



